

License No. : AISPS9337E
Expiry : 22.01.2014

Mobile No. : 9336913591
Phone No. : (0542)2214682
E-Mail : ak_vns@yahoo.co.in

ANIL KUMAR SRIVASTAVA
SURVEYOR & LOSS ASSESSOR
C-23/44A, KABIR CHOURA, VARANASI-221091

REF NO : AFI/U-Bns/9014/13

DATE : 08.07.2013

FINAL SURVEY REPORT

This report is issued by me as licenced surveyor without prejudice, in respect of cause, nature and extent of loss damage and subject to the terms and condition of the insurance policy.

1. **INSURER** : United India Insurance Co. Ltd., Bulandshahar
26, Civil Lines Bulandshahar.
2. **INSURED** : Mr. Rajat Singh Jain S/o Mr. N. S. Jain
D 146, 1st Floore, Gate no. 1 Suraj Mal Vihar Delhi
3. **POLICY PARTICULAR**
 - a) Policy Cover note No : 2220023113P100622523
 - b) Period of Insurance : 30.04.2013 to 29.04.2014
 - c) Insured Declared Value : Rs. 1,30,000/-
 - d) H.P.A. with : None

११९९ ३

4. **VEHICLE PARTICULARS** : (Noted From Original R. C.)

- a) Registered No : DL 4 CU/ 8572
- b) Dt. of Registration : 02.03.2007
- c) Chassis No : 600631ASZP20261
- d) Engine No : 475SI56ASZP18285
- e) Make/Model : Tata Motors Ltd., (Xeta GLS) 02/2007
- f) Type of body : Saloon
- g) Class of vehicle : L.M.V (Car)
- h) Pre accident condition : Average
- i) R.L.W/Seating capacity : 5 in all
- j) U.L.W : 1405 Kgs.
- k) Road tax paid up to : Final One Time Tax paid.
- l) Fitness valid up to : N.A
- m) Permit No : N.A
Valid up to : N.A
Type of permit : N.A
- n) Route/Area of operation : N.A

5. **DRIVER PARTICULAR** : (Noted from Original D.L.)

- a) Name & Address of Driver : Sri. Vishwanath S/o Sri. S. Kharwar
- b) M.D.L.No : C88/THR/88263
- c) Date of issue : 07.01.1988
- d) Valid up to : 17.02.2015 w.e.f 09.02.2012
- e) Issuing authority : L. A. Mumbai West
- f) Authorized to Drive : HGV and endorsed for M/cycle W.e.f 22.12.1993

6. **ACCIDENT PARTICULAR** :

- a) Date and time of accident : 15.05.2013 at about 6.30 P.M
- b) Place of accident : Near Badlapur, distt. Jaunpur
- c) Place of Survey : At M/s Ani motors, Muradgunj, Jaunpur.
- d) Date of Allotment of Survey : 16.05.2013
- e) Date and Time of Survey : 16.05.2013 and other onward dates.

[Handwritten Signature]



License No. : AISPS9337E
Expiry : SLA 22210
: 22.01.2014

Mobile No. : 9336913591
Phone No. : (0542)2214682
E-Mail : ak_vns@yahoo.co.in

ANIL KUMAR SRIVASTAVA
SURVEYOR & LOSS ASSESSOR
C-23/44A, KABIR CHOURA, VARANASI-221001

DATE : 08.07.2013

REF NO : AFI/U-Bns/9014/13

7. CAUSE OF ACCIDENT : As per Claim form that subject vehicle was passing through the place of accident, suddenly a cycle man came before the subject vehicle and in effort to save him, subject vehicle dis-balanced and gone off the road and collided with the tree.
In the opinion of Undersigned cause of accident & nature of damage is relevant & practicably possible.

8. T.P. LOSS/ INJURY, IF ANY : Nil

9. POLICE FORMALITIES : Nil.

10. ESTIMATE : The Insured has submitted the Estimate of M/s Ani motors, Muradgunj, Jaunpur. for Rs. 96993.00

11. LOAD / PASSENGER DETAILS : Only one person was seated inside the vehicle at the time of accident.

12. UNIT NO : (NOTED PHYSICALLY)
a) Chassis No : 600631ASZP20261
b) Engine No : 475SI56ASZP18285
c) Kms. Reading : 46662 Kms
d) Battery Make : Exide freedom

13. SPOT REPORT : Spot Survey not conducted.

14. DAMAGE DETAILS : Bonnet pressed, Tie member pressed, Both side Head light broken, Radiator & condenser pressed, Radiator fan pressed, RH Fender pressed, RH eyebrow broken, Air Filter broken, Radiator lower support pressed, Both side Fender lining broken, power steering pulley pressed, tie rod bent, suspension arm bent, shocker bent.

15. ASSESSMENT OF LOSS OF VEHICLE NO : DL 4 CU / 8572

A.	NEW PARTS	
1.	Hood shell	Rs. 05879.00
2.	Fender Assy .RH	Rs. 03005.00
3.	Tie member Assy.	Rs. 03865.00
4.	Cover plate cross mbr	Rs. 00860.00
5.	Hood Hinges Assy.	Rs. 00275.00
6.	Hood hinges Asy.	Rs. 00266.00
7.	Condenser assy.	Rs. 16500.00.
8.	Radiator Assy.	Rs. 04744.00
9.	Radiator Bottom support	Rs. 00932.00
10.	Suspension Arm Assy, Front RH	Rs. 02864.00
11.	Front shocker Assy. RH	Rs. 02885.00
12.	Horn 12 V	Rs. 00890.00
13.	Hood latch cable	Rs. 00098.00
14.	Power steering hose	Rs. 00248.00
15.	Power steering pulley	Rs. 00504.00
16.	Power stg. Shaft	Rs. 00348.00
17.	Wheel Rim	Rs. 01044.00
18.	Ball joint pwr stg	Rs. 00405.00
	To Balance C/f	Rs. 45612.00

Policy No. : AISPS9337E
License No. : SLA 22210
Expiry : 22.01.2014

Mobile No. : 9336913591
Phone No. : (0542)2214682
E-Mail : ak_vns@yahoo.co.in

ANIL KUMAR SRIVASTAVA
SURVEYOR & LOSS ASSESSOR
C-23/44A, KABIR CHOURA, VARANASI-221001

DATE : 08.07.2013

REF No : AFI/U-Bns/9014/13

19. To Balanced B/f
20. Tie Rod
A.C. hose

Add Vat 14 %

Less Dep. 40 %

21. Head lamp RH
22. Front Bumper Assy.
23. Fog lamp Bezel RH
24. Fog lamp Bezel LH
25. Hood strip Assy.
26. Hood insulation
27. Front Eyebrow RH
28. Air Filter Assy.
29. Radiator Fan Assy.
30. Splash Guard Front bumper
31. Fender lining Front RH
32. Power stg brg

Add Vat 14 %

33. Painting Materials

Less Dep. 50 %

Rs. 45612.00
Rs. 00324.00
Rs. 00835.00
Rs. 46771.00
Rs. 06547.94
Rs. 53318.94
Rs. 21327.57
Rs. 31991.37 Rs. 31991.37

Rs. 03752.00
Rs. 04892.00
Rs. 00208.00
Rs. 00208.00
Rs. 00350.00
Rs. 00920.00
Rs. 00410.00
Rs. 01548.00
Rs. 06800.00
Rs. 00398.00
Rs. 00644.00
Rs. 00396.00
Rs. 20526.00
Rs. 02873.64
Rs. 23399.64
Rs. 01500.00
Rs. 24899.64
Rs. 12449.82
Rs. 12449.82

Rs. 12449.82
Rs. 44441.19 Rs. 44441.19

TOTAL NEW PARTS ALLOWED
B. REPAIRS & LABOUR :

34. Engine labour
35. Electrical labour charges
36. Denting cutting, welding of tie member,
Denting of Lh Fender, Cowl top
37. Painting of Dented and replaced parts up to color match
38. Opening & Fitting of Body parts
39. Ac Gas filling charges

40. Chassis aligning charges
41. Towing & Spot labour charges

TOTAL FOR REPAIRS & LABOUR
Total For A + B =

Less Policy Excess

NET PAYABLE AMOUNT

Rs. 01000.00
Rs. 00500.00

Rs. 03500.00
Rs. 04500.00
Rs. 01500.00
Rs. 01500.00

Rs. 04000.00
Rs. 01500.00
Rs. 18000.00

Rs. 18000.00
Rs. 62441.19
Rs. 01000.00
Rs. 61441.19

SALVAGE : Expected salvage value Rs. 1500.00

RE-INSPECTION : I Have Carried the Re-inspection of the above vehicle and repairs / replacement are executed as per above given assessment. I took 5 Nos. of photographs of the repaired vehicle.

Encl:

1. S.F.BILL
2. P/Copy of R.C, D.L, Policy
3. 25 Nos of Digital Photographs
4. Estimate, Claim form

(A. K. SRIVASTAVA)